1. Click scantool_net113w

www.obd2express.co.uk



3. Click “I agree”.



4. Click “Next”


ScanTool.net for Windows v1.13 Setup
Choose Components
Choose which features of ScanTool.net for Windows v1.13 you want to install.
Check the components you want to install and uncheck the components you don't want to install. Click Next to continue.
Select components to install:
Source Code
Description
Position your mouse over a component to see its description.
Space required: 764.0KB
Nullsoft Install System v2.11
< Back
Next >
Cancel

5. Click “Next”


ScanTool.net for Windows v1.13 Setup
Choose Install Location
Choose the folder in which to install ScanTool.net for Windows v1.13.
Setup will install ScanTool.net for Windows v1.13 in the following folder. To install in a different folder, click Browse and select another folder. Click Next to continue.
Destination Folder
C:\Program Files\ScanTool.net_win
Browse...
Space required: 764.0KB
Space available: 2.6GB
Nullsoft Install System v2.11
< Back
Next >
Cancel

6. Click “Install”

7. Finish

ScanTool.net for Windows v1.13 Setup
Completing the ScanTool.net for Windows v1.13 Setup Wizard
ScanTool.net for Windows v1.13 has been installed on your computer.
Click Finish to close this wizard.
Run ScanTool.net for Windows v1.13
Show Readme
< Back
Finish
Cancel

8.USB Driver

9. Start to setup by the advanced way as following shows: