

## **SUBJECT**

Enabling Codes (FSC) Required After CIC Replacement

## **MODEL**

E82, E88 \*(1 Series)

E90, E91, E92, E93 \*(3 Series)

**\*with option 609 (Navigation System Professional)**

**Vehicles from September 2008 onward**

## **SITUATION**

After replacing the Car Information Computer (CIC), the following functions are inoperative:

Navigation System

Voice Recognition System

## **CAUSE**

Enabling codes (FSC) are required to activate the navigation and voice recognition systems.

## **PROCEDURE**

**NOTE: If, during the course of diagnosis, a CIC needs to be replaced, the only part that should be installed is a new part that has not been previously installed in a vehicle. The CIC enabling codes are VIN-specific and if installed in another vehicle, the Navigation System and the Voice Recognition System (SVS) will not function. Do not swap parts from donor vehicles.**

In the EPC (Electronic Parts Catalog), always order the three enabling codes together with a replacement CIC:

CIC Navigation Enabler Release Code (to activate Release Code functionality)

CIC Navigation Application Release Code (to activate the navigation function)

CIC Voice Repair Release Code (to activate voice control SA620)

These three enabling codes will be supplied via ASAP.

Download the enabling codes on ASAP.

**NOTE: The enabling codes that are downloaded via ASAP are in a compressed file format. The file must be uncompressed, and the contents copied to the root directory (not in a folder) of a blank formatted floppy disk, on a USB or burned to a CD.**

Load the Release Codes when prompted by Progman or ISTA/P.

WARRANTY INFORMATION For information only